


Drill Hole 1A

Porosity Water
Saturation


0% 30% 0% 100%



Drill Hole InCross

Porosity Water
Saturation


0% 30% 0% 100%



Drill Hole InCross

Porosity Water
Saturation

0% 30% 0% 100%



Drill Hole 3A

Porosity Water
Saturation

0% 30% 0% 100%

